


TRUCK UTILITY 3/4 TON, GS, FFR, LANDROVER  
REAR BODY FLOOR  
UNIT REPAIR

Introduction

1. This instruction supersedes DEME BULLETIN 20/68, and details the drilling of the rear body floor of vehicle to prevent an accumulation of water causing damage to the C.A.V. suppression box mounted on the rear body front panels.

Detail

2. From under the vehicle drill two 1/2 inch diameter holes in the positions shown in Fig 1.



DIMENSIONS ARE IN INCHES

FIG. 1 -- RIBS UNDER REAR BODY FLOOR

(TSU M 382/69)

END

Distribution - Class 68.2 - Code No 4

RESTRICTED