

TRUCK, UTILITY 1/4 TON GS LANDROVER

RE-SEALING - CANOPY FRONT SEAM

UNIT REPAIRS

SUMMARY

1. This instruction details the sealing of front seams to prevent further parting.
2. *Items affected:-*
Covers canopy nylon (2510-66-011-1525)
3. *Action required by* Units and RAEME workshops affected to note and observe this instruction.
4. *Stores required:-*

<i>Sec/Cat No</i>	<i>Designation</i>	<i>Qty Per Veh</i>
NIV. NIV	Brella sealer 801 type "E" Brella sealer 801 accelerator	As required As required

NOTE:- Sealer is available from:-

Brella Pty Ltd
4 Ralph St
Reservoir. Vic.

Brella Pty Ltd
Parramatta Rd
Camperdown. NSW.

W.R.Porter
307 Queen St
Brisbane. Qld

Johnson and
Sons
28 Linsey St
Perth. WA.

DETAIL

5. Proceed as follows:-
When failure of original seam sealing agent is evident reseal using sealer vide para 4.

E N D