

TRUCKS COMMAND RECONNAISSANCE 1/4 TON
LANDROVER

TAIL GATE

SUMMARY

1. This instruction details a method of overcoming difficulty in sliding stores across the tailgate when lowered. Estimated manhours to perform: 1/2

2. Items affected:-

2510-66-010-7744 TAILGATE, vehicle, body.

3. Action required:-

In accordance with GEN A 017 less sub paras 7b and 7c.

DETAIL

4. The method is firstly to beat the edge of the lip on the outer edge of the tailboard down to the tailboard floor, and secondly to beat the rivets securing the tailboard runners, down below the level of the top of the runners, thereby allowing stores etc to slide freely, and preventing damage to the tailboard. Proceed as follows

- (a) Ensure that the gap under the lip of the tailboard is clean and free from obstruction.
- (b) Using a light hammer and dolly, beat the edge of the lip down to the floor of the tailboard.
- (c) Beat any projecting rivets below the level of the top of the runners, again using light hammer and dolly.
- (d) Paint in accordance with WKSPS J 700.

E N D