

## CAV ALTERNATOR AC 724-1

### UNIT REPAIRS

#### INTRODUCTION

1. Material used in construction of the brackets on this equipment can be easily distorted, causing poling or complete seizure of the armature.

#### REPAIRS

2. When, for any reason, this unit is removed from the vehicle the number of spacers removed will be noted, labelled, and tied together. On no account will the Alternator be replaced on the vehicle, unless the number of spacers removed are available for replacement.

E N D