

## LANDROVER, ALL TYPES

### VOLTAGE REGULATOR

#### UNIT WORK

#### INTRODUCTION

1. Much of the trouble that exists with the charging system can be attributed to poor earthing; this should be one of the first points to check. Cases of poor earthing of the regulator box are often due to the shakeproof washer on the earthing terminal being fitted in the wrong position.

#### WORK INFORMATION

2. When checking the charging system ensure that this washer is fitted between the terminal eyelet and the head of the drive screw and *NOT* between the terminal and the engine bulkhead.

E N D