

TRUCKS, UTILITY, 1/4 TON AND 3/4 TON GS, LANDROVER
FUEL TANK COVER PLATES

MODIFICATION INSTRUCTION

REFERENCE:- AGs in WM Nos 22227/26, 22228/21, 23614/2, 23850/2.

SUMMARY

1. This instruction details the enlargement of the fuel tank dipstick access hole in the seat cover plate to permit the waterproofing of the fuel tank dipstick assembly.
Estimated manhours to perform: 0.5

2. Priority: Group 2

3. Vehicles affected:

Subject vehicles.

4. Items affected:

Seat cover panel for fuel tank

5. Action required: By RAEME workshops authorised to carry out field repair in accordance with WKSP A 850.

DETAIL

6. (a) Remove the seat cover panel for the petrol tank.
- (b) Enlarge the 1 1/4 inch diameter dipstick access hole to 1 3/4 inch diameter.
- (c) Refit the cover panel.

E N D