

TRUCK, UTILITY, 1/4 TON AND 3/4 TON, LANDROVER

FORMATION AND UNIT SIGN HOLDERS

MODIFICATION INSTRUCTION

REFERENCE:- ACs in WM Nos 22227/18, 22228/12.

SUMMARY

1. This instruction details the fitting of vehicle formation and unit sign holders to the front and rear of the vehicle in the positions detailed in Standing Orders for Vehicle Operation and Servicing, section 20, para 117 and 118.

Estimated manhours to perform: 1.0

2. Priority: Group 2

3. Vehicles affected:

Subject vehicles not fitted with formation and unit sign holders.

4. Action required: By RAEME authorised to carry out unit work or repair in accordance with WKSP A 850.

5. Items affected:

Front mudguards and rear panel

6. Stores required: Obtainable through normal channels.

Item No	Sec/Cat No	Designation	Qty per Veh
1	2590-66-016-0815	HOLDER, veh unit and formation sign plate, 5 in x 5 in sign	4
2	5310-66-013-0065	WASHER, lock, spring steel, single turn, sq sec, 3/16 in bolt size, cad plated	12
3	5310-66-013-1408	NUT, plain, hex, BSF, FF, bright, 3/16 in	12
4	5310-66-014-8477	SCREW, machine, BSF, free fit, MS, flat csk hd, zinc coated, 3/16 in x .2 in	12

DETAIL

7. The formation and unit signs will be positioned as follows:-

(a) Formation Signs -

LH front mudguard adjacent flasher and parking light group, LH rear panel adjacent tail and flasher light group.

(b) Unit Signs -

RH front mudguard adjacent flasher and parking group.  
RH rear panel adjacent tail and flasher light group.

NOTE:- Where the rear panel differs as on special vehicles ie, Fire Tenders etc, the holders will be placed as near as possible to the above positions.

8. Paint in accordance with WKSP B 700.

E N D